

Project Case No.		PUGET SOUND CLEAN AIR AGENCY 110 Union Street, Ste. 500 Seattle, WA 98101-2038 (206) 689-4090 fax (206) 689-4073 www.pscleanair.org	Date Received: <i>Agency Use Only</i>
QUARTERLY REPORT			

1st QTR DUE APRIL 15 – 2nd QTR DUE JULY 15 – 3rd QTR DUE OCTOBER 15 – 4th QTR DUE JANUARY 15

Property Owner: The Boeing Company			Work Schedule: M T W Th F Sa Su Hours: 06:00 to 14:30
Mailing Address: P.O. Box 3707, 12-AP			Contact Person: Bill Whelan
City: Seattle	State: WA	Zip: 98124	Phone No.: 206-655-8497

IMPORTANT: DO NOT INCLUDE ANY OTHER ASBESTOS PROJECTS FILED UNDER SEPARATE NOTIFICATION FORMS. THE QUARTERLY REPORT SHALL ONLY APPLY TO PROJECTS WHERE THE SUM TOTAL OF ALL THE ASBESTOS REMOVALS FROM EACH STRUCTURE, VESSEL OR BUILDING IN A CALENDAR YEAR IS LESS THAN 260 LINEAR FEET AND 160 SQUARE FEET.

ASBESTOS REMOVAL PROJECTS UNDERTAKEN DURING THE 1st QUARTER FOR CALENDAR YEAR 2006

FACILITY NAME: Boeing Renton Division Property **TELEPHONE:** 206-655-8497

PROJECT DATES		JOB SITE ADDRESS OR LOCATION Specify Name of Bldg., Vessel, etc.	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete				Quarter	Year Total
1/30/06	1/30/06	Renton Site Facility Bldg No.: 4-21 Address or Location 8th Street and Park Ave. North City Renton	1. <u>Nhat Truong</u> 2. <u>Oliver Udani</u> 3. _____ 4. _____	2006022761 200601974A _____ _____	20 LF	

METHOD OF REMOVAL (describe): Glove bag removal of 20 LF of ACM MAG pipe insulation.

COMPLIANCE PROCEDURES (describe): _____

* Continue on Next Page for Additional Projects

ANTICIPATED ASBESTOS REMOVAL PROJECTS FOR NEXT QUARTER: _____

I do hereby certify that the information contained in this Quarterly Report and supplemental data described herein is to the best of my knowledge, accurate and complete.			Agency Use Only
_____ <i>Signature</i>	The Boeing Company _____ <i>Representing</i>	_____ <i>Date</i>	_____ <i>Reviewed By</i>

QUARTERLY REPORT (Continued)

ASBESTOS REMOVAL PROJECTS UNDERTAKEN DURING THE 1st QUARTER FOR CALENDAR YEAR 2006

PROPERTY OWNER: The Boeing Company

Page 2 of 2

PROJECT DATES		JOB SITE ADDRESS OR LOCATION	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete	Specify Name of Bldg., Vessel, etc.			Quarter	Year Total
2/3/06	2/3/06	<u>Renton Site</u> Facility _____ Bldg No.: _____ Address or Location _____ <u>8th Street and Park Ave. North</u> City <u>Renton</u>	1. <u>Dale Riel</u> 2. <u>Kendall Lysene</u> 3. _____ 4. _____	<u>200610415A</u> <u>2006019185A</u> _____ _____	1 SF	

METHOD OF REMOVAL (describe): Disposal of a valve with intact PACM gaskets and packing material.

COMPLIANCE PROCEDURES (describe): _____

PROJECT DATES		JOB SITE ADDRESS OR LOCATION	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete	Specify Name of Bldg., Vessel, etc.			Quarter	Year Total
3/17/06	3/17/06	<u>Renton Site</u> Facility _____ <u>Building: 4-82</u> Address or Location _____ <u>8th Street and Park Ave. North</u> City <u>Renton</u>	1. <u>Mike Hubbard</u> 2. <u>Oliver Udani</u> 3. _____ 4. _____	<u>2006009531A</u> <u>200601974A</u> _____ _____	6 LF	

METHOD OF REMOVAL (describe): _____

COMPLIANCE PROCEDURES (describe): _____

PROJECT DATES		JOB SITE ADDRESS OR LOCATION	ASBESTOS CONTRACTOR OR EMPLOYEE NAMES	CERT #	QUANTITY REMOVED In Linear or Square Feet	
Start	Complete	Specify Name of Bldg., Vessel, etc.			Quarter	Year Total
		<u>Renton Site</u> Facility _____ Bldg No.: _____ Address or Location _____ <u>8th Street and Park Ave. North</u> City <u>Renton</u>	1. _____ 2. _____ 3. _____ 4. _____	_____ _____ _____ _____		

METHOD OF REMOVAL (describe): _____

COMPLIANCE PROCEDURES (describe): _____

* Attach Continuation Page for Additional Projects